

Features:

- Non-Hazardous/High-Flashpoint
- Low-VOC/Low Odor
- No SARA or Prop 65 Reportable Ingredients
- Non-Toxic
- Non-Chlorinated
- Contains NO Petroleum Distillates
- High-Solvency Meets or Exceeds Boeing D6-17487 Revision L Spec.



WATER-RINSABLE DEGREASER/ ADHESIVE REMOVER PRODUCT OVERVIEW

The versatile solvent, Powerful enough for the toughest jobs!

Bradley Systems' Water-Rinsable Degreaser/Adhesive Remover was designed to safely remove grease, oil, tar, asphalt, and adhesive from both painted and non-painted surfaces. Our Water-Rinsable Degreaser/Adhesive Remover is created from refined vegetable oils, is non-toxic, and contains low VOCs.

Bradley's **Water-Rinsable Degreaser/Adhesive Remover** has been proven in the field for effective and efficient performance.



A DIVISION OF TRION CHEMICALS® 320 37th Avenue • St. Charles, IL 60174 1-800-252-1114 • www.bradley-systems.com

For pricing, more information and to order: call 1-800-252-1114 or email bradleysystems@trionchemicals.com



WATER-RINSABLE DEGREASER/ ADHESIVE REMOVER SPECS & APPLICATIONS

Applications:

- Adhesive removal
- Grease & Oil removal
- Tar & Asphalt removal
- Cars, Trucks, Buses
- Metal Surfaces
- Machinery Parts

... from both painted and non-painted surfaces

Usage Directions:

Cars, Trucks and Buses: Quickly removes adhesive, grease, tar, asphalt and oil from both painted and non-painted surfaces. Safe on most painted surfaces, but test in an inconspicuous area for compatibly, first. Spray product on the area to be cleaned and work into the soil. For removal of adhesive on painted surfaces, a soft plastic scraper might be needed to lift off the adhesive. Be careful not to scratch or damage the surface with any tool. Once the job is done, simply rinse with water.

Bare Metal Surfaces: Removes all tar, asphalt, grease, oil and grime from engines and chassis of autos, trucks, buses and tractors quickly and economically. It is ready to use. Simply spray the area to be cleaned using a low-pressure sprayer. Allow to remain on for ten or fifteen minutes and flush away with water. Use soft bristle brush for stubborn soils if necessary. Cover any electrical contacts.

Machinery Parts: Place parts in a tank. Allow to soak for one half hour to two hours depending upon the accumulation of grease or tar on the part. Remove parts and wash with water from a hose. A stiff bristle brush may be used for caked on grease.

For pricing, more information and to order: call 1-800-252-1114 or email bradleysystems@trionchemicals.com



Available Configurations:



